

HISTORIC PRESERVATION CERTIFICATION

APPLICATION — PART 1

(Pursuant to the Tax Reform Act of 1976)

Instructions: Applicant should read the instructions carefully before completing application. No Certification may be made unless a completed application form has been received (P.L. 94-455). Use typewriter or print clearly in dark ink to complete the application form. If additional space is needed to complete Part 1, use the reverse side or a separate plain sheet of paper clearly indicating the owner's name and mailing address. Part 1 of this application may be completed and sent to the appropriate State Historic Preservation Officer at any time during the year, and may be sent separately or with Part 2.

PART 1 EVALUATION OF SIGNIFICANCE

1. NAME OF PROPERTY:

Address of property: Street 643 South Paca Street
City Baltimore County N/A State Maryland Zip Code 21230
Name of historic district in which property is located Ridgely's Delight

2. DESCRIPTION OF PHYSICAL APPEARANCE:

(see instructions for map and photograph requirements—use reverse side if necessary)

(See reverse)

3. STATEMENT OF SIGNIFICANCE:

(use reverse side if necessary)

This house conforms to the style of this historic district.

Date of construction (if known) 1825 (Approx.) ☒ Original site ☐ Moved Date of alterations (if known) _____

4. NAME AND MAILING ADDRESS OF OWNER:

Name Joseph K. Burton
Street 6561 Bock Terr
City Oxon Hill State Maryland Zip Code 20745
Telephone Number (during day) Area Code (202) 767-5548

I hereby attest that the information I have provided is, to the best of my knowledge, correct, and that I am owner of the property described above

Signature Joseph K. Burton Date Jan 12, 1983

For office use only

The structure described above is included within the boundaries of the National Register historic district and ☒ contributes ☐ does not contribute to the character of the district

The structure ☐ appears ☐ does not appear to meet National Register Criteria for Evaluation (36 CFR 60.6) and ☐ will likely ☐ will not be nominated to the National Register in accord with the Department of the Interior procedures (36 CFR 60).

The structure is located in a district which ☐ appears ☐ does not appear to meet National Register Criteria for Evaluation (36 CFR 60.6). ☐ will likely ☐ will not be nominated to the National Register in accord with Department of the Interior procedures (36 CFR 60) and ☐ appears ☐ does not appear to contribute to the character of said district.

Signature J. Mittle Date 7-5-83
State Historic Preservation Officer

This property has been evaluated according to the criteria and procedures set forth by the Department of the Interior (36 CFR 67) and, if subject to depreciation under section 167 of the Internal Revenue Code of 1954,


☐ is hereby certified a historic structure.

☐ does not contribute to the character of the historic district and does not merit certification as a historic structure. Reasons given on the attached sheet:

Signature _____ Date _____
Keeper of the National Register

- 2) The house at 642 S. Tara Street is a combination of a 2 1/2 story, two story and one story structure. It has an overall depth of 64 feet. The 2 1/2 story section fronts on Paca Street - is 15 feet wide and 30 feet deep. The two story section is 9 1/2 feet wide and 21.3 feet deep and the one story section is 11.7 feet wide and 12.7 feet deep. The 2 1/2 story section fronting on Paca Street (Picture 3 & 15) is constructed of smooth brick with fine joints. This type of construction is typical of urban dwellings of the late Federalist Period. The rear wing or "back building" (Picture #4) is characteristic of houses of this type built after 1820. As is typical of this period the back building on the second floor is a stair landing lower than the front section. The first floor passage from the main building to the back building contains a side entrance (Picture #5). This side entrance door has the sidelights that are also characteristic of the period. The rear of the main building and the back building (Picture #4) have the lintel type window heads of the period. The lintel and sidelight sills of the side entrance door (Picture #5) are similarly constructed. At the rear of the lot, fronting on Burgandy Street (Picture #7) is a separate 1 1/2 story brick structure occupying the full lot (15 foot) width and is 22.4 feet in depth.


B-3901
643 S. Paca Street
Block 0861 Lot 039
Baltimore City
Baltimore West Quad.



B-3901




#1 - View from
second floor looking
toward Harbor -



#2 - View from second
floor - shows rear
of houses fronting
on Fremont St.

B-3901

← #3 - Front view of
643 Paca St. (and house)
Before Rehab.



#4 →

Side yard and rear
view of 643 Paca St.
Before Rehab.

